

SERVICE BULLETIN

Four-Ball Pump Changes

LOWER PUMP ENDS AFFECTED: 6720X-X


RELEASED: 7-6-99
REVISED: 1-10-12
REV: 00
BULLETIN: #5-99
FORM: 4336-2

Changes affect models built after 6-30-99 (SN F9309XXX).

The following changes were made to 6720X-X Lower Pump End.


- 1.) Add 92425 gaskets (2).
- 2.) Add 92424 ball seats (2).
- 3.) Add 93508-1 ball.
- 4.) Add 94936 spacer.
- 5.) 94507 and 94664 followers are machined to accept the items listed above.

OLD DESIGN



NEW DESIGN

(After June 30, 1999)



PN 97999-1600

INGERSOLL RAND COMPANY LTD

209 NORTH MAIN STREET - BRYAN, OHIO 43506

☎ (800) 495-0276 • FAX(800) 892-6276

www.ingersollrandproducts.com

© 2012

CCN 46735072

ARO

IR Ingersoll Rand
Industrial Technologies