


SERVICE BULLETIN

RELEASED: 4-11-07
REVISED:
(REV. 01)
BULLETIN: #1-07

1/2" Diaphragm Pumps MODELS AFFECTED: See list below.

The following changes were made:

1. Item 139, 93116 "U" cup (nitrile) replaced by 96383 (polyurethane).
2. Change effects models and service kits built beginning April 23, 2007 (S/N D0237XXX or GD0237XXX).



Models Affected:

650728	650764	666056-XXX	670022
650732-X	650766-XXX	666057-XXX	670031-XXX
650736-1X	650768	66605H-XXX	670034
650742	650776	66605J-XXX	670036-050
650743	650778-XXX	66605K-XXX	670040-XXX
650744	650781-XXX	670003-XXX	670041-XXX
650746	650782-XXX	670004	670043
650747	650783-XXX	670006	727312
650757-XXX	650788	670007-XXX	PD05P-AAS-XXX
650758-XXX	650789-XXX	670009	PD05P-ASS-XXX
650759	650792	670013-XXX	PM05P-CSS-XXX-A02
650760	650794	670014	
650761-XXX	650795	670018	
650762-XXX	666053-XXX	670020	

Service Kits Affected:

61995-1	637263
637141	637264
637141-G	637267
637262	637321

PN 97999-1258

INGERSOLL RAND COMPANY LTD
P.O. BOX 151 • ONE ARO CENTER • BRYAN, OHIO 43506-0151
① (800) 276-4658 • FAX (800) 266-7016 © 2007 CCN 15283757

ARO

IR Ingersoll Rand
Industrial Technologies