

# SERVICE BULLETIN


## 1/2" and 3/4" Diaphragm Pump Changes PX05X-XXX-XXX-B, PX07X-XXX-XXX, 6700XX

RELEASED 9-19-08  
REVISED:  
(REV. 01)  
BULLETIN: #2-08

The following changes were made:

1. Item "118" actuator pin (pn 94874-1, 1.047" long) replaced with (pn 97111, 0.885" long).

This change is effective on models built after September 30, 2008 (serial number I0308XXX).



### Models Affected:

670042  
670047  
670054  
670056  
670057  
670058  
670077

PD05A-XXX-XXX-B  
PD05P-XXX-XXX-B  
PD05R-XXX-XXX-B  
PD07P-XXX-XXX  
PD07R-XXX-XXX  
PE05A-XXX-XXX-B  
PE05A-XXX-XXX-B05

PE05P-XXX-XXX-B05  
PE05R-XXX-XXX-B  
PE05R-XXX-XXX-B05  
PE07P-XXX-XXX-A05  
PG05A-XXX-XXX-B  
PM05R-XXX-XXX-B02

PN 97999-1404

INGERSOLL RAND COMPANY LTD  
P.O. BOX 151 • ONE ARO CENTER • BRYAN, OHIO 43506-0151  
(800) 276-4658 • FAX (800) 266-7016  
fluids.ingersollrand.com

© 2008

CCN 15300098

# ARO

**IR** Ingersoll Rand  
Industrial Technologies