Description:

This is the release of Insight ICD & ICM Controller Software version R.1.3.0. Only customers with bugs addressed or those that require the features below should be upgraded. This is for use with MCE version R.3.2.0 and Language version R.1.3.0

Restrictions:

Version 1.3.0 can only be used with ICS (PC) version 1.2.0. If you upgrade the controllers, you MUST upgrade the ICS software.

New Features:

- Fully compatible with ICS Connect, ICS Multisync, and ICS Network (ICS version1.2.0)
- Enhanced messages on Run Screen

Known Bugs in R.1.3.0:

- The USB port is not operational in this version.

- The controller does not reliably reboot after downloading software to the controller from ICS. When the controller fails to restart within the time described in the Software Loading procedure, manually restart the system.

See AS 040905 JMR2 for ICS Software Loading and Licensing Instructions
See AS 082005 JM for ICD & ICM Software Loading using ICS
See AS 100105 JM for ICS Software Version 1.2.0

Ingersoll-Rand   Zimmerman   Johnstone   FTS   Aro