

SERVICE BULLETIN

2.062 Sq. In. and 4.125 Sq. In. Motor Changes

MODELS AFFECTED: 67147, 67314 and 67325

RELEASED: 11-15-06

REVISED:


(REV. 01)

BULLETIN: #2-06


The following changes were made:

1. 94559 springs replaced by 96611 springs.
2. Add 96609 spring followers.
3. 94550 trip plugs replaced by 96610 trip plugs.
4. 94557 trip rod replaced by 96626 trip rod.
5. Add Y145-4 retaining ring.
6. 95906 retainers replaced by 96627 trip washers.
7. Remove 94788 spacer.

OLD MOTOR - 4.125 Sq. Inch



NEW MOTOR - 4.125 Sq. Inch



Model Number

67147

67314

67325

Conversion Kit

637451

637452

637452

Convert to Model Number

67147-B (see page 2)


67314-B

67325-B

The following changes were made:

1. 94559 springs replaced by 96611 springs.
2. Add 96609 spring followers.
3. 94550 trip plugs replaced by 96610 trip plugs.
4. 94557 trip rod replaced by 96626 trip rod.
5. Add Y145-4 retaining ring.
6. 94560 retainers replaced by 96628 trip washers.
7. Remove 94788 spacer.

OLD MOTOR - 2.062 Sq. Inch



NEW MOTOR - 2.062 Sq. Inch

