

SERVICE BULLETIN

93727-1 Piston (Item 107) Length Change

SB10x-x-x Shock Blocker Models

RELEASED: 12-16-11


REVISED:

(REV. 00)

BULLETIN: #4-11

Changes affect Shock Blockers manufactured after 18 November 2011 (S/N xK1181-xxx)
All Manufacturing Locations

The length of 93727-1 changed from 3.250 to 3.468 to improve performance of the
66911-1 Air Tamer Assembly



97999-1604

INGERSOLL RAND COMPANY LTD
209 NORTH MAIN STREET - BRYAN, OHIO 43506
(800) 495-0276 • FAX(800) 892-6276
www.ingersollrandproducts.com

© 2010 CCN 46735155

ARO

IR Ingersoll Rand
Industrial Technologies