

SERVICE BULLETIN

FP2009-002 Revision 0 04-Sept-2009

Before performing any service always follow applicable safety precautions. Consult company safety manual or supervisor for questions concerning safety.

ARO-Flo Series – Regulator and Filter/Regulator Pressure Adjustment

Affected Products: P39XXX-2XX, P39XXX-4XX, R37XXX-2XX, and R37XXX-4XX

Affected Date Range: N/A

Related Issue #: QRMS: 2009TFM-1104

Issue Description:

Adjustment range can exceed spring rating on 0-30 psi and 0-60 psi regulators. The working range of the adjustment knob is designed to permit outlet pressures beyond the spring ratings in the 0-30psi and 0-60psi models. The adjustment knob is not designed to be a pressure limiting device. This design is common for most industrial regulators. Limiting devices may be obtained only by special design. For optimal performance, regulators should not be set to ranges outside the specified spring range.

Actions Required:

N/A

Material Disposition:

N/A

Additional Comments:

N/A

Recommended 2nd Level Distribution:

Regional Service Center Managers, Regional Solution Center Managers, Regional Sales Managers, Authorized Distributor Service Centers Distribute to all Regional Technical Support and Regional Service Personnel.

For Additional Information:

Contact Ingersoll Rand Solution Center in your region:

Americas: +1 (248) 293-5700

European Served Area: +33 1 64 76 00 00

Asia Pacific: +86.21.6463.8018

India: +91-120-4389400