

INSTRUCTIONS FOR INSERT KIT MP3084-7

This brass insert may be used to repair MQ2829-2 cylinders and upgrade MQ2829 and MQ2829-1 cylinders to MQ2829-2. Seal repair kit MP2829-30 is required.

This insert may be used to repair MQ3084 cylinders. Seal repair kit MP3084-20 is required.



INGERSOLL-RAND COMPANY

ONE ARO CENTER • BRYAN, OHIO 43506-0151

 (419) 636-4242 • FAX (419) 636-2115

©1996 • PRINTED IN U.S.A.

PN / 119999-054 5-96

INGERSOLL-RAND
FLUID PRODUCTS