



Application Services (866) 284-5509

Technical Bulletin: AS 031105 JM

"No Cal" Problem in ETW-A

Problem:

The screen on an ETW-A wrench "NO CAL" and the wrench will not operate.



Cause:

There was a problem in manufacturing several of these wrenches that allowed them to lose their calibration after a very brief period of time.

To Fix:

Contact Technical Support at (866) 284-5509 to have the wrench sent in for repair.

Repair times are usually 8 to 10 business days.